

GigaDevice Semiconductor Inc.

Device Limitations of GD32A503

Errata Sheet

Table of Contents

Table of Contents	2
List of Figures	4
List of Tables	5
1. Introduction	6
1.1. Revision identification	6
1.2. Summary of device limitations	6
2. Descriptions of device limitations	8
2.1. FMC	8
2.1.1. Power failure/reset results in MCU crash when write operation is performed for EEPROM...	8
2.1.2. When the START command is sent after MER and FSTPG are set, PGSERR error flag is not set	8
2.2. PMU	8
2.2.1. Frequent wake-up signal before and after MCU enters the standby mode results in wake-up failure in the standby mode.....	8
2.2.2. MCU resets twice during the power-on process.....	9
2.3. BKP	9
2.3.1. Reading of BKP_DATA register after BKPRST is set results in MCU crash.....	9
2.4. RCU	9
2.4.1. MCU in deep sleep mode cannot be woken up after DSLP_HOLD bit in DBG register is set 9	
2.5. MFCOM	10
2.5.1. When TMOUT is set to 0b'10 or 0b'11 under the condition that MFCOM is used as a UART receiver, the reset function of the timer encounters error	10
2.5.2. When the baud rate is low under the condition that MFCOM is used as a UART receiver, the receiving of the data after the second frame encounters error.....	10
2.6. DBG	11
2.6.1. MCU cannot enter the debug mode from the standby mode after STB_HOLD bit in DBG register is set.....	11
2.6.2. MCU in the standby mode cannot be woken up after STB_HOLD bit in DBG register is set 11	
2.7. ADC	11
2.7.1. Over 5 V input voltage of PB13 pin results in incorrect voltage sampling of PD14 pin	11
2.8. USART	12
2.8.1. Negative narrow pulse interference results in wrong data received by the serial port	12
2.9. TIMER	12
2.9.1. CHxCAPFLT and CHxCAPPSC can be set only if the bit is set twice after converting from the	

output mode to the input mode in PROT mode 2	12
2.9.2. A constantly high or low level in a cycle of PWM is output when the duty ratio is over 50% in the composite PWM mode.....	12
2.10. CAN	13
2.10.1. Reset of USART0/USART1 peripheral results in communication error of CAN0/CAN1	13
2.10.2. CAN mailbox 0 converted from receiving mailbox to transmitting mailbox fails to send the data frame.....	13
2.10.3. As a transmitting node, CAN executes unexpected self-calibration function	13
2.10.4. CAN manual bus off recovery function faults	14
3. Revision history	15

List of Figures

Figure 1-1. Device revision code of GD32A503 6

List of Tables

Table 1-1. Applicable products	6
Table 1-2. Device limitations	6
Table 3-1. Revision history.....	15

1. Introduction

This document applies to GD32A503 product series, as shown in [Table 1-1. Applicable products](#). It offers technical guidance for using GD32MCU and provides workaround to current device limitations.


Table 1-1. Applicable products

Type	Part Numbers
MCU	GD32A503xx series

1.1. Revision identification

The device revision can be identified according to the mark on the top of the package. The 1st code on Line 3 of the mark is the product revision code, as shown in [Figure 1-1. Device revision code of GD32A503](#).

Figure 1-1. Device revision code of GD32A503



1.2. Summary of device limitations

The device limitations of GD32A503 are shown in [Table 1-2. Device limitations](#), please refer to Section 2 for more details.

Table 1-2. Device limitations

Module	Limitations	Workaround
		Rev. Code B
FMC	<i>Power failure/reset results in MCU crash when write operation is performed for EEPROM</i>	N
	<i>When the START command is sent after MER and FSTPG are set, PGSERR error flag is not set</i>	Y
PMU	<i>Frequent wake-up signal before and after MCU enters the standby mode results in wake-up failure in the standby mode</i>	N
	<i>MCU resets twice during the power-on process</i>	N
BKP	<i>Reading of BKP_DATA register after BKPRST is set results in</i>	Y

Module	Limitations	Workaround
		Rev. Code B
	<i>MCU crash</i>	
RCU	<i>MCU in deep sleep mode cannot be woken up after DSLP_HOLD bit in DBG register is set</i>	Y
MFCOM	<i>When TMOUT is set to 0b'10 or 0b'11 under the condition that MFCOM is used as a UART receiver, the reset function of the timer encounters error</i>	Y
	<i>When the baud rate is low under the condition that MFCOM is used as a UART receiver, the receiving of the data after the second frame encounters error</i>	Y
DBG	<i>MCU cannot enter the debug mode from the standby mode after STB_HOLD bit in DBG register is set</i>	Y
	<i>MCU in the standby mode cannot be woken up after STB_HOLD bit in DBG register is set</i>	Y
ADC	<i>Over 5 V input voltage of PB13 pin results in incorrect voltage sampling of PD14 pin</i>	Y
USART	<i>Negative narrow pulse interference results in wrong data received by the serial port</i>	N
TIMER	<i>CHxCAPFLT and CHxCAPPSC can be set only if the bit is set twice after converting from the output mode to the input mode in PROT mode 2</i>	Y
	<i>A constantly high or low level in a cycle of PWM is output when the duty ratio is over 50% in the composite PWM mode</i>	Y
CAN	<i>Reset of USART0/USART1 peripheral results in communication error of CAN0/CAN1</i>	Y
	<i>CAN mailbox 0 converted from receiving mailbox to transmitting mailbox fails to send the data frame</i>	Y
	<i>As a transmitting node, CAN executes unexpected self-calibration function</i>	N
	<i>CAN manual bus off recovery function faults</i>	Y

Note:

Y = Limitation present, workaround available

N = Limitation present, no workaround available

'-' = Limitation fixed

2. Descriptions of device limitations

2.1. FMC

2.1.1. Power failure/reset results in MCU crash when write operation is performed for EEPROM

Description & impact

Power failure or reset of MCU results in data error of EEPROM in write operation, which causes system crash.

Workarounds

Not available.

2.1.2. When the START command is sent after MER and FSTPG are set, PGSERR error flag is not set

Description & impact

PGSERR error does not occur when START is set after MER and FSTPG in FMC_CTL0 register are set during operation in bank0 area.

Workarounds

Make sure that MER and FSTPG are not set at the same time in the software during operation in bank0 area.

2.2. PMU

2.2.1. Frequent wake-up signal before and after MCU enters the standby mode results in wake-up failure in the standby mode

Description & impact

When the internal signal STBY_CTL is reset to allow MCU to enter the standby mode, if Tglitch is less than 100 ns, MCU cannot be woken up because of incorrect output of Vcore due to narrow glitch.

Note: Tglitch is the time from low level of STBY_CTL to wake-up signal (PA0 is a high level).

Workarounds

Not available.

2.2.2. MCU resets twice during the power-on process

Description & impact

POR and BOR act on NRST successively, which will cause NRST to have a 60us high level to low level then high level process and cause MCU to reset twice.

Workarounds

Not available.

2.3. BKP

2.3.1. Reading of BKP_DATA register after BKPRST is set results in MCU crash

Description & impact

Reading of BKP_DATA register after BKPRST bit in RCU_BDCTL register is set results in MCU crash.

Workarounds

Make sure that BKPRST is reset when BKP_DATA register is being read.

2.4. RCU

2.4.1. MCU in deep sleep mode cannot be woken up after DSLP_HOLD bit in DBG register is set

Description & impact

MCU in deep sleep mode cannot be woken up by EXTI after DSLP_HOLD bit in DBG register is set.

Workarounds

Switch the system clock to internal IRC8M before MCU enters the deep sleep mode.

2.5. MFCOM

2.5.1. When TMOUT is set to 0b'10 or 0b'11 under the condition that MFCOM is used as a UART receiver, the reset function of the timer encounters error

Description & impact

When TMOUT is set to 0b'10 or 0b'11, the reset function of the timer encounters error. When TMOUT output is opposite to the configured TMOUT, the reset signal set for TMRST will flip the TMOUT output. The lower 8 bits of the counter will be reloaded, but the operation of decrementing the higher 8 bits by one is not performed, causing an additional clock output by TMOUT.

Workarounds

- 1) When MFCOM is used as a serial port receiver, properly decrease TMCVALUE in TMCMPx register, and increase the baud rate.
- 2) When MFCOM is used as a serial port receiver, set TMRST[2:0] to 0'b000 (never reset the timer) and TMSTOP[1:0] to 0b'00 (disable the stop bit).

2.5.2. When the baud rate is low under the condition that MFCOM is used as a UART receiver, the receiving of the data after the second frame encounters error

Description & impact

When the baud rate of the serial port is low, the valid start bit of the next data cannot be received due to TMEN signal loss during counting of the stop bit, which causes the error in receiving subsequent data.

Workarounds

- 1) When MFCOM is used as a serial port receiver, properly decrease TMCVALUE in TMCMPx register, and increase the baud rate.
- 2) When MFCOM is used as a serial port receiver, set TMRST[2:0] to 0'b000 (never reset the timer) and TMSTOP[1:0] to 0b'00 (disable the stop bit).

2.6. DBG

2.6.1. MCU cannot enter the debug mode from the standby mode after STB_HOLD bit in DBG register is set

Description & impact

MCU cannot enter the debug mode from the standby mode after STB_HOLD bit in DBG register is set.

Workarounds

Switch the system clock to internal IRC8M before MCU enters the standby mode.

2.6.2. MCU in the standby mode cannot be woken up after STB_HOLD bit in DBG register is set

Description & impact

MCU in the standby mode cannot be woken up after STB_HOLD bit in DBG register is set.

Workarounds

Switch the system clock to internal IRC8M before MCU enters the standby mode.

2.7. ADC

2.7.1. Over 5 V input voltage of PB13 pin results in incorrect voltage sampling of PD14 pin

Description & impact

As PB13 pin and PD14 pin belong to the same group of ADC multiplex channel (ADC1_IN15), over 5 V input voltage of PB13 pin results in electric leakage of PMOS on PB13 pin, then voltage increase of ADC1_IN15 to be close to 5 V, and finally PMOS breakover on PD14 pin, so that the voltage of PD14 pin is equal to that of ADC1_IN15.

The above case applies to any group of IO port with the same multiplex function among ADC.

Workarounds

Taking the IO port of PB13/PD14 pin as an example, increase the operating voltage of MCU so that the voltage of VDD/VDDA/VREF+ is equal to the maximum voltage on PB13 pin.

Note: As the reference voltage is changed, ADC conversion processing should be changed

accordingly in the software. In this case, users should evaluate the system impact of such change.

2.8. USART

2.8.1. Negative narrow pulse interference results in wrong data received by the serial port

Description & impact

Negative narrow pulse interference on the receiving data cable (Rx) of the serial port results in detection of wrong start bit by USART and data receiving error.

Workarounds

Not available.

2.9. TIMER

2.9.1. CHxCAPFLT and CHxCAPPSC can be set only if the bit is set twice after converting from the output mode to the input mode in PROT mode 2

Description & impact

When complementary registers are set to PROT mode 2 for protection control and TIMER is converted from the output mode to the input mode, CHxCAPFLT and CHxCAPPSC bit fields can be set only if CMxMS bit in CHCTLx register is set twice.

Workarounds

Operation is not affected.

2.9.2. A constantly high or low level in a cycle of PWM is output when the duty ratio is over 50% in the composite PWM mode

Description & impact

A constantly high level in a cycle of PWM is output when the duty ratio is updated from over 50% to below 50% in composite PWM mode 0; a constantly low level in a cycle of PWM is output when the duty ratio is updated from below 50% to over 50% in composite PWM mode 1.

Workarounds

Disable the shadow register in software, and update the comparative threshold through DMA request.

2.10. CAN

2.10.1. Reset of USART0/USART1 peripheral results in communication error of CAN0/CAN1

Description & impact

Setting USART0RST bit in RCU_APB2RST register or USART1RST bit in RCU_APB1RST register results in operation failure of CAN0/CAN1 during CAN communication and data receiving error.

Workarounds

In the software, first initialize USART0/USART1 and then CAN0/CAN1, and do not reset initialized USART0/USART1.

2.10.2. CAN mailbox 0 converted from receiving mailbox to transmitting mailbox fails to send the data frame

Description & impact

CAN mailbox 0 converted from receiving mailbox to transmitting mailbox fails to send the data again after sending a frame of data.

Workarounds

In the software, convert the receiving mailbox to the transmitting mailbox after reading the data in the receiving mailbox.

2.10.3. As a transmitting node, CAN executes unexpected self-calibration function

Description & impact

When the delay (Tx-Rx readback time + 2*CK_CAN) is over a Tq, as a transmitting node, CAN executes self-calibration, which results in broadening of sent dominant level and communication error.

Workarounds

Not available.

2.10.4. CAN manual bus off recovery function faults

Description & impact

When the CAN is in bus off state due to bus short or other bus exception, which cause bus to remain in a recessive state, after enabling the CAN automatic bus off recovery (ABORDIS) function, the bus off recovery flag (BORF) will be set. If CAN is still at bus off state at this time, the bus off flag (BOF) will be set again. If bus off interrupt (BOIE) and bus off recovery interrupt (BORIE) are enabled, the corresponding interrupt process will be entered ceaselessly.

Workarounds

Stop mailbox transmission before enabling and disabling automatic bus off recovery function. Taking CAN1 as an example, the following reference code can be called in manual bus off recovery scenario.

```
{  
    /* stop mailbox transmission */  
    transmit_message.code = CAN_MB_TX_STATUS_ABORT;  
    can_mailbox_config(CAN1, 1, &transmit_message);  
    /* enable then disable bus off recovery function */  
    can_auto_busoff_recovery_enable(CAN1);  
    can_auto_busoff_recovery_disable(CAN1);  
}
```

3. Revision history

Table 3-1. Revision history

Revision No.	Description	Date
1.0	Initial Release	Nov.20, 2023

Important Notice

This document is the property of GigaDevice Semiconductor Inc. and its subsidiaries (the "Company"). This document, including any product of the Company described in this document (the "Product"), is owned by the Company under the intellectual property laws and treaties of the People's Republic of China and other jurisdictions worldwide. The Company reserves all rights under such laws and treaties and does not grant any license under its patents, copyrights, trademarks, or other intellectual property rights. The names and brands of third party referred thereto (if any) are the property of their respective owner and referred to for identification purposes only.

The Company makes no warranty of any kind, express or implied, with regard to this document or any Product, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. The Company does not assume any liability arising out of the application or use of any Product described in this document. Any information provided in this document is provided only for reference purposes. It is the responsibility of the user of this document to properly design, program, and test the functionality and safety of any application made of this information and any resulting product. Except for customized products which has been expressly identified in the applicable agreement, the Products are designed, developed, and/or manufactured for ordinary business, industrial, personal, and/or household applications only. The Products are not designed, intended, or authorized for use as components in systems designed or intended for the operation of weapons, weapons systems, nuclear installations, atomic energy control instruments, combustion control instruments, airplane or spaceship instruments, transportation instruments, traffic signal instruments, life-support devices or systems, other medical devices or systems (including resuscitation equipment and surgical implants), pollution control or hazardous substances management, or other uses where the failure of the device or Product could cause personal injury, death, property or environmental damage ("Unintended Uses"). Customers shall take any and all actions to ensure using and selling the Products in accordance with the applicable laws and regulations. The Company is not liable, in whole or in part, and customers shall and hereby do release the Company as well as its suppliers and/or distributors from any claim, damage, or other liability arising from or related to all Unintended Uses of the Products. Customers shall indemnify and hold the Company as well as its suppliers and/or distributors harmless from and against all claims, costs, damages, and other liabilities, including claims for personal injury or death, arising from or related to any Unintended Uses of the Products.

Information in this document is provided solely in connection with the Products. The Company reserves the right to make changes, corrections, modifications or improvements to this document and Products and services described herein at any time, without notice.